

PYA 2019 Profile





Automotive Group












"WE ARE COMMITTED TO SATISFYING OUR CLIENT'S CURRENT AND FUTURE NEEDS, ALWAYS IMPROVING THE QUALITY OF OUR PRODUCTS, FOLLOWING A MINDSET OF ZERO DEFECTS AND ENVIRONMENTAL AWARENESS."











Who is PYA?

" PYA, headquartered in Mexico City and Irapuato is a Mexican Tier 1 manufacturer for the Automotive Industry that has over 38 Years of experience"











- 1995 Plastic division is founded
- 1996 Robert bosch braking components
- 1997 Vel-Con incorporates PYA's CVJ boots for GM
- 1998 Plant relocation to meet expanding needs
- 2000 Design department created
- 2001 Laboratory expansion MTS , weatherometer

2002 – ISO9002 / QS9000

2003 – Tyco Electronics electric box developed

2004 – ISO TS16949


- 2005 PVC water strips Sekurit Saint Gobain
- 2006 PYA USA created
- 2007 PVC water strip developed for Vitro
- 2011 Kinugawa Is a new Customer for PYA



"TO BECOME A GREEN LEADER IN PRODUCT INNOVATION AND NEW MATERIAL SUPPLY IN NORTH AMERICA ACROSS OUR BUSINESS UNITS."

















O Products
























2K and Paint





























NCTPS























O Models











































CLIENTS





Machines



50T - 1800T





Awards





NNA-SQD

4/23/2019

MONTHLY QUALITY REPORT FOR NORTH AMERICAN REGIONAL SUPPLIERS- MARCH 2019 (Plant Level)

Region: NNA

Supplier: 1792000-POLIMEROS Y AMIANTOS SA DE CV CUAUTITLAN IZCALLI Global Code: 2N46

Address: ALESSANDRO VOLTA #34, PARQUE INDUSTRIAL CUAMATLA CUAUTITLAN, EM

Score		Status			Index	Total Index	Туре	Category Points		Performance		
						Points		Performance	Target Achieve	Actual	Target	TA Ratio
99.1 / 100		1	\odot		SP-3MIS	34.1 / 35	3MIS Warranty	22.9	11.2	1.4 IPM	4.0 IPM	0.3
99.1 / 1	.00				Ranking	35.0 / 35	Disruptions	23.0	12.0	0.0	2.0	0.0
		10161	and the second	12	PPM	10.0 / 10	Delivery Quality	7.0	3.0	0.0 PPM	1.1 PPM	0.0
						Design	3.5	3.0	0.0 Days	87.0 Days	0.0	
Performance Indicator				Q-Speed	10.0 / 10	Manufacturing	3.5	3.0	0.0 Days	23.0 Days	0.0	
Rank Level	L1	L2	L3	L4	Response	10.0/10	Plant Rating	10.0		10.0	10.0	
Points	90-100	80-89	60-79	<60	R/S Occur	(0.0)	Recall / Service	0.0		0.0	0.0	-
Status Indicator	Meets Expectations			8	P/M Occur	(0.0)	Port Modification	0.0		0.0	0.0	
					Production Prep	(0.0)	Production Prep	0.0		0.0	0.0	-
			Marginal	Improvement Required	ePPM	(0.0)	Export Part Quality	0.0				
					Change Mgmt	(0.0)	FSCR / PCR	0.0		-		

Year to Date Status (As of Reporting Month)

Zero Defects	Excellence,	Master of Quality
1992 to 1994, 1998, 2000, 2002,2007,2008,2010	1996	1997 to 2002

Month) Quality Index Breakdown (12 Month Rolling)



Testing



CMM MTS Simulated weather tests Weatherometer Reometer Optical comparator 3D modeling Color Test Gloss Test
















Assembly









For further information please contact:

Germán Carrasco Commercial Director, PYA germanj@pyaglobal.com +52 (1) 55 2271 2112



www.pyaautomotive.com